

ANNEX F

Warranty for Engines and Original Spare Parts –
Warranty Process

**IVECO
MOTORS**

Industrial Warranty Procedures Engines

Iveco Motors Limited Warranty Terms

Effective date November 1st, 2004

Revision June 2006

Terms and Conditions General warranty statement:

2 year limited warranty coverage; the warranty applies to new engines sold to customers anywhere in the world where Iveco Motors approved service is available. The guarantee consist exclusively of the supply, free of charge for parts that can not be used on the account of a factory defect in material or workmanship subject to prior ascertainment of the cause of said defects. The simple cost of labor for replacing the part or parts is the liability of the engine manufacture, Iveco Motors. The customer or owner of the engine is responsible for the removal and replacement of the engine if need be for parts replacement. (Amendment to Annex F)

1st Year Full Engine Coverage. Unlimited hours total coverage for components supplied by Iveco Motors. Plus the parts and repair labor time.

2nd year Limited Coverage Select components only listed below. Plus the repair labor time.

Engine block	Timing gears
Sleeves	Oil pump
Crankshaft	Exhaust manifold
Connecting rods	Pistons
Flywheel	Cylinder head
Camshaft	Bosch ECU

The starter and alternator are covered up to 3000 total original hours or 24 months which ever comes first.

Irrigation program application only: 24 months or 3000 hours full engine coverage which ever comes first; the first 12 months is unlimited hours.

Standby Generator Applications

60 months or 2000 hours; maximum usage 400 hours per year.

Iveco Motors of North America

Attn: Product Support Department

245 E. North Ave.

Carol Stream, IL 60188

Phone 630-260-4238

Fax 630-260-4267

Email archie.emmert@iveco.com

Applicability of the guarantee

The guarantee is not applicable in the following cases:

- If the engine has been used in any way that does not conform with the indications provided by Iveco Motors (handling errors, overloading, use of unsuitable fuels or lubricants, poor quality coolant and not just limited to these conditions).
- In the event of the unfulfilled observance of maintenance standards, including periods during which the engines are not being used the guarantee will be voided.
- If the failure is the outcome of an installation procedure that does not conform within specifications or if the engines have been modified and/or repaired without following the conditions or repair procedures represented in the Iveco Motors application or manuals.

The purchaser explicitly and specifically accepts the guarantee rules contained here and, consequently, may not insist on annulment of the contract or claims for damages.

Warranty Registration Certificate

The purpose of the warranty registration certificate is to register each engine with Iveco Motors.

The certificate information must provide the shipping date to the customer, with engine serial number and model; submitted to email to archie.emmert@iveco.com. Within 10 days of delivery to validate the warranty. Amendment to Annex F.

The Warranty start date will begin on the date of delivery to the customer. If the *Revalidation of Guarantee for the long term stored engines has been followed.*

Revalidation of Guarantee for the long term stored engines

Iveco Motors does not encourage long term storage but there may be conditions in which it will not be possible to sell an engine to the first end-user within 12 months from the date of dispatch from the factory. Therefore the engine must be re-treated every 12 months after delivery from Italy according to the following procedures:

1. Carefully check all drive belts and the v-groove in the pulley for corrosion.
2. Drain all existing oil in the sump and in the injection pump.
3. Replace the lub, oil filter and fill the sump and pump regulator house with protective oil MIL-L-2160 B type 2 or equivalent product.

4. Connect the fuel feeding line at pump side with a supply of CFB oil (ISO 4131).
5. Filling the cooling system with inhibited coolant.
6. With the stop control in the “stop position” turn the engine on the starter motor until oil pressure is built up.
7. Run the engine for 15 minutes at 500-800 rpm; and at the end, using syringe, slowly (1 minute) introduce in the inlet manifold the following quantity of MIL-L-2160 type 2 or equivalent product:

3-4 cylinder engines and bank of 8 cylinder engines. 60 gr.

6 cylinder engines. 120 gr.

12 cylinder engines per bank. 80 gr.

8. Stop the engine and drain the inhibition oil. The oil can be used to inhibit 2 other engines.
9. Remove the fuel supply re-connect the line.
10. If coolant is left in the system, the raw water must have adequate Paraflyu' 11 additions to prevent the possibility of future frost damages otherwise drain the ensuing that no water remains in the engine and in the coolers.
11. Loosen the belts and ensure that all open apertures (air intakes, exhaust manifold, etc.) are securely sealed.
12. Store the engines under shelter in an area not subject to extreme variations in temperature and humidity and label them with “no oil” notices.
13. When this procedure is completed, register this with Iveco Motors in order to have reinstatement of the shelf-life warranty of up to a total period of 24 months.

The purchaser is liable for:

1. Out of pocket travel expenses.
2. Labor expenses deriving from dismantling, replacement and transport of the engine to and from the user's premises,
3. Expense derived from the use of cranes or other equipment needed to remove and/or re-install the engine and working needed to make the engine accessible for all the various operations.

4. Taxes and all other sums due and not foreseen by the guarantee.

Handling of Failed Warranty Parts

- All parts must be tagged and cleaned (unless cleaning destroys the evidence), plus stored in a protected place from the elements.
- **Service parts are required to be held until your company receives reimbursement for the warranty claim.** When your company receives reimbursement, the part or parts can be scrapped.
- Failed part or parts photos may be required. IVECO kindly asks your company to make use of digital cameras when necessary.
- IVECO will be responsible for all freight charges regarding returned parts for warranty inspection.

The Annex F applies for all other conditions; Warranty for Engines and Original Spare Parts-Warranty Process.

North American only Service Reimbursements Rates

Labor:

Shop posted labor will be paid. Rate must be on file at IVECO Motors of North America. If posted shop labor is not on file, the authorized repair center will be paid \$50.00 per hour for warranty reimbursement until a labor request form has been submitted to IVECO Motors. IVECO Motors will pay reasonable engine removal and replacement when necessary for a warranty repair.

Travel time:

The travel time rate will be paid at a value of 80% of the posted shop labor rate on file with IVECO Motors for reasonable travel times.

Mileage:

Should be calculated at .55 per mile for the round trip. 1 round trip. A maximum of 300 miles but not limited to this range.

Service Parts:

The total reimbursement for the Service part or parts used in the warranty repairs is calculated as:

Total parts credit = Distributor Net Price + Parts Profit [Dist. net price for part x 20%].

Outside expenses:

When reasonable and justified; invoices are required.

Warranty Claim Procedure

- All Claims must be filled out properly and be legible; they can be either typed or hand written in black ink.
- The claim must include delivery date with model, serial number and hours of service. Sample claim included.
- One failure per claim is allowed unless this claim is regarding a catastrophe failure.
- In order to process the claim in a reasonable amount of time, the claim must be submitted with 21 days of the repair completion.
- All additional miscellaneous expense must have appropriate invoices attached to claim or the process will be delayed unless those receipts have been received by the Product Support Department.
- The failure must have a clear, understandable and decisive explanation on the claim. "Defective" is not a sufficient description.
- All claims must have a signature from the authorized service center manager.

Iveco Motors of North America
Attn: Product Support Department
245 E. North Ave.
Carol Stream, IL 60188
Phone 630-260-4238
Fax 630-260-4267
Email archie.emmert@iveco.com